

FOREVER GmbH • Robert-Bosch-Str. 43 • D-68542 Heddesheim **Phone:** +49 (0) 62 03/ 930 20 - 0 • **Fax:** +49 (0) 62 03/930 20 - 40

E-mail: info@forever-ots.com • Web: www.forever-ots.com



HEAT TRANSFER INSTRUCTIONS

Instructions for Printing onto Dark Colored Textiles with FOREVER Ink-Jet Dark

IMPORTANT!

Only for Ink-Jet Printers suitable! NOT with irons transferable!

PRINT SETTINGS

Image Mode: No mirror image

Feeding: Manuell

>>> TRANSFER SETTINGS

	AU	UTOMATIC HEAT PRESS	MANUAL HEAT PRESS
PRESSURE		5 bar (70 PSI)	High/maximum
TEMPERATURE		180° - 200° C (390° F)	180° - 200° C (390° F)
TIME	Press	s 5 sec. with application tape 30-20 seconds	Press 5 sec. with application tape 40-30 seconds

TRANSFER APPLICATION

- ▶ Print the image.
- ▶ Cut the outlines.
- ▶ Place the application tape on the printed areas, rub under pressure and mirror on it.
- ▶ Weed the unprinted areas off the application tape.
- ▶ Remove the backing paper from **FOREVER Ink-Jet Dark.**
- ▶ Place the application tape Solvent with the printed areas on the garment.
- ▶ Press for 3-5 seconds.
- ▶ Remove the application tape immediately.
- ▶ Cover the image with **Glossy Finish** (Antistick) or **High Gloss** and press again for 30 seconds.

WASHING

▶ Up to 40° C (cold wash cycle). Do not use bleach. Do not tumble dry.

IRONING

▶ When ironing cover the print with baking paper.

ANY PROBLEMS? Visit our website www.forever-ots.com

Click Video, choose the transfer paper, transfer machine, the product and watch the specific application!