

FOREVER GmbH • Robert-Bosch-Str. 43 • D-68542 Heddesheim **Phone:** +49 (0) 62 03/ 930 20 - 0 • **Fax:** +49 (0) 62 03/930 20 - 40

E-mail: info@forever-ots.com • Web: www.forever-ots.com



HEAT TRANSFER INSTRUCTIONS

Instructions for Printing onto Light Colored Textiles with FOREVER Ink-Jet Basic WT (red grid on the back side)

for 100% Cotton

▶ PRINT SETTINGS

IMPORTANT!

Only for use in ink-jet printers and with dye-based or pigment inks.

Image Mode: Mirror Image

► TRANSFER SETTINGS

	AUTOMATIC HEAT PRESS	MANUAL HEAT PRESS
PRESSURE	3 bar (43.5 PSI)	medium
TEMPERATURE	174°C (345°F)	174°C (345°F)
TIME	20 seconds	20 seconds

TRANSFER APPLICATION

- ▶ Place the textile on the lower plate of the transfer press.
- ▶ First press the t-shirt during a few seconds.
- ▶ Place FOREVER Ink-Jet Basic WT onto the t-shirt.
- ▶ Press for 20 seconds.
- ▶ Peel off the transfer paper after cooling down completely, then smoothly and evenly peel away the backing paper.

▶ WASHING

Wash inside out in cold wash cycle.

▶ IRONING

Do not iron directly on transferred image.

ANY PROBLEMS? Visit our website www.forever-ots.com

Click Video, choose the transfer paper, transfer machine, the product and watch the specific application!